PORT SHEPSTONE

KANTEY & TEMPLER

可含义的制度的信息的人的形式

JOHANNESBURG CURATIO BLDG ROADWAY CENTRE

SANNET ROAD P.O BOX 91867 AUCKLAND PARK DURBAN 4000

155 MOORE ROAD GLENWOOD PO. BOX 82 28 BAZLEY ST PO BOX 399 PORT SHEPSTONE 4240

66 VICTORIA ST P.O. BOX 458 GEORGE 6530

GEORGE

OUDTSHOORN 37 BARON VREEDE ST OUDTSHOORN

PLETTENBERG BAY 2 CUPID ST PLETTENBERG BAY

TEL (011) 482 2103/17 FAX 482 3455

TEL (031) 3014455 FAX 3014444

TEL (0441) 74 2177/8 FAX 741364 TEL (0391) 22511/2 FAX 824439

TEL (0443) 291768 FAX 291881

TEL (04457) 3 3200 FAX 3 3200

FFICE:

PE TOWN

George

OUR REF:

G3636

YOUR REF:

DATE:

18 January 1995

OUR NEW STREET ADDRESS 66 VICTORIA STREET

Mr I Alder P O Box 377 WILDERNESS 6560

Dear Sir

REMAINDER OF ERF 1: WILDERNESS: GEOTECHNICAL INVESTIGATION

This report is compiled in accordance with the requirements of the Wilderness Local Council as set out in paragraph 2.3 and the "Rioolbeskikking" of headed 14/7/2/927 dated 25 August 1994.

The remainder of erf 1, hereinafter called "the site", is located between the national road N2 and the Map of Africa road. site is somewhat broken but slopes generally to the South East. Slopes vary from 1:7 to 1:1. Only those parts of the site with slopes flatter than 1:4 will be developed.

The site is covered with indigenous bush and trees. surface consists of a layer of rich humus approximately 100 mm thick over clay over weathered rock.

There is no evidence of hard rock on the surface or in trial holes dug at the sites of proposed houses. and locality sketch are appended.

The upper reaches of the site is underlain by phyllites, schists, hornstones and quartzites of the Soetkraal member of the Kaaimans formation. The Soetkraal member dips towards the south at between 20° and 35°.

Rock anchors have been used at Dolphin's Point to stabilise the cut slope of the N2 however it is most unlikely that slips in the national road cut will occur that will effect buildings erected at the positions selected on the site. Should rock be encountered in excavations it must not be removed without first consulting a Geotechnical Engineer as the dip is at such an angle that slips could be caused in higher lying materials.

B P SCHROEDER
R P TWEMLOW
W J VAN DER MERWE
K G MILLAM
I M WILLIAMS
R A DURDEN
A G POLLARD
C A ROSE
B N CROSS
A B JORDANN

A B JORDAAN GSTLOWDEN PI Eng C Eng MISITUCIE MSAICE MSAACE
PIEng PhD BSC MICE MISITUCIE MASCE MSAICE MSAACE
PISCHAI MSC[Eng Geol) CEng DIC MIMM MSAIEG
PIEng BSC[Eng) MSAICE MSAACE
PIEng BSC[Eng) MSAICE MSAACE
PIEng MICE MSAICE MSAACE
PIEng MICE MSAICE MSAACE
PIEng MICE MSAICE MSAACE
PIEng MS[Eng) BSC[Eng) FSAICE MSAACE
PIEng MS[Eng) MSAICE MSAACE
PIEng BSC[Eng) MSAICE MSAACE
PIEng MSC[Eng) MSAICE MSAACE
PIEng MSC BSC[Eng) MSAICE MSAACE
PIEng MSC BSC[Eng) MSAICE MSAACE

REGIONAL PARTNER CONSULTANT

P D TOWNSHEND B D WILSON

PiEng BSc(Eng) MSAICE MICE FIMESA PrEng BSc(Eng) MSAICE

ASSOCIATES SOILS

LABORATORIES

D J AYRES F DU PLESSIS N HIRSCHMAN CAPE 10WN

H MARSH

PORT SHEPSTONE

LB COX GR TYNDALL GBAKER GEORGE

