


Annexure K: Photographs

Activities carried out on Portion 12 of the Farm Ongegunde Vryheid No 746, Cape st Francis

DEDEAT reference: SBROB#2021-05-21



Front of main cottage showing raised decking over old access track facing east



Main cottage showing access track behind dwelling facing east

Activities carried out on Portion 12 of the Farm Ongegunde Vryheid No 746, Cape st Francis

DEDEAT reference: SBROB#2021-05-21



Facing south of main cottage showing rocky seashore



Facing north of main cottage showing intact vegetation



Second cottage developed mostly on footprint of the previous dwelling



Second dwelling prior to renovation showing approximate footprint



Photographs showing construction of second dwelling in progress



Imagery showing second dwelling prior to renovation with indication of footprint



Imagery showing second dwelling prior to renovation post to renovation with indication of footprint